

Product Safety Recall

Lithium Battery Systems — Lithium Iron Phosphate Batteries 24110-SP and 36110-SP



Sold in NT and QLD between July 2020 and Feb 2022

DESCRIPTION

24V 110Ah & 36V 110Ah lithium iron phosphate batteries, typically used in marine applications. Includes 24V & 36V Whitehaven series batteries.

Affected model numbers: 24110-SP-MRN, 24110-SP-VM-MRN, 36110-SP-MRN, 36110-SP-VM-MRN, 24110-SP-WHIT-MAR & 36110-SP-WHIT-MAR.

DEFECT

The battery may overheat, vaporising the internal liquid into a toxic gas which vents from the battery.

HAZARD

If the battery overheats and vents gas, it can cause severe skin and/or eye irritation and damage/corrode property. If the gas vents into an enclosed area, poisoning could occur, resulting in serious illness, injury, or death.

If the gas vents in the presence of an ignition source, there is an increased risk of a fire.

WHAT TO DO

Consumers should stop using the battery and electrically isolate and store the battery in a cool location. Consumers should return the battery to the place of purchase to arrange for the battery to be replaced or repaired.

CONTACT DETAILS

For further information, consumers can contact Lithium Battery Systems by email (with Subject 'Recall') at support@lithiumbatterysystems.com.au

**See productsafety.gov.au for
Australian product recall information**