



Product safety recall

Knog Blinder Front Bicycle Lights

Recalled Products:

Blinder 900, Blinder 1300, Blinder StVZO 80, Blinder StVZO 120

Recalled Batch Codes:

Blinder 1300, StVZO 80 and StVZO 120: 0423-AA, 0723-AA, 0923-AA, 1023-AA, 1123-AA, 11A23-AA, 0124-AA

Blinder 900: 0423-AA, 0723-AA, 0923-AA, 1023-AA, 1123-AA, 0721-AA, 0823-AA, 1223-AA



Reason the product is recalled

Blinder bicycle lights with an affected batch code contain lithium-ion batteries that may fail and catch fire.

The hazards to consumers

Risk of serious burn injury & property damage if the battery catches fire. Incidents have occurred.

What consumers should do

1. Stop using the affected Blinder front bicycle light immediately.
2. Check the batch code using the [Knog product recall portal](#).
3. If your light is affected, follow the instructions on the [Knog product recall portal](#) to receive a free replacement bike light.
4. Dispose of the affected bike light in accordance with local regulations for lithium-ion batteries. Improper disposal can lead to environmental hazards and safety risks.

Knog Contact Details

Call +61 1800 299 321 between 08:30 am and 05:30pm AEST, Mon to Fri

Email: recall@knog.com

Visit <https://www.knog.com/recall>



Who sold the product: www.knog.com and authorised retailers in Australia via BikeCorp.

Dates available for sale: 1 January 2023 to 15 June 2025

PRA2025/20608

See productsafety.gov.au for Australian product recall information