



# Product Safety Recall



## Do you own this product?

**Fluke Australia Pty Ltd - Fluke-17XX, flat cable, voltage test lead 3-phase+N cables and associated kits**

These cables were sold separately as 3PHVL- 17XX cable replacement kits and included with the following kits:

- Fluke-3540 Power Monitors
- 173x Series Power Loggers
- 174x Series Power Quality Loggers
- 177x Series Power Quality Analyzers

Affected cables will have either:

- A date wheel on a moulded plastic clip over the cables. The first wheel shows a two-digit year code and the second wheel shows a month number. Codes between 21-04 and 21-11 are recalled; or
- A code on the longer end of the L1/A cord showing a manufacturer code followed by a two-digit month and two-digit year. Codes between 04/21 and 11/21 are recalled.

Dates sold: 1 April 2021 to 30 November 2021



**Why the product is recalled:** The black moulded plastic insulators may crack, exposing the user to the metal parts of the connector and the risk of direct contact to an electrical current.

**Hazard:** Risk of serious injury or death from electric shock.



Stop using the product immediately and check the date code to see if the cable is affected. If the date code is illegible or missing, contact Fluke for more information.

Consumers with affected cables should cut the cable in half to make it unusable and register for a free replacement on the recall webpage.



For more information, consumers can visit the recall webpage <https://www.fluke.com/en-au/support/safety-notices/17xx-quadcable-recall>, phone 1300 135 853 or email [ordersanz@fluke.com](mailto:ordersanz@fluke.com).

PRA 2023/19854

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information