



# Product Safety Recall

## Various Seat Adapter Kits for Falcon BA-FGX and Commodore VE Seats



**Old kit - with defect**



**New kit - without defect**

Sold by Huracan Fabrication between 15 March 2018 and 6 June 2019

**Defect:**

At loads exceeding 1.2 tonne seat belt strain, the seat belt mounting point may fail, resulting in the seat belt buckle breaking loose.

The product does not meet the required Australian Design Rule 'Vehicle Standard (ADR 3/03 - Seats and Seat Anchorages) 2006.'

**Hazard:**

If seat belt buckle breaks in the event of an accident, the seat occupant is at risk of serious injury or death.

**What to Do:**

Consumers should contact Huracan Fabrication to receive seat belt mount upgrade kit, free of charge.

**Contact Details:**

For more information, contact Huracan Fabrication via email [admin@huracanfabrication.com](mailto:admin@huracanfabrication.com)

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**