



Auto-Set Wedge Bracket installed on certain Malibu Response TXi Boats





Sold by Authorised Malibu Boats Dealers between 12 April 2017 and 12 February 2020

Defect The upper mounting bolts used on the Auto-Set Wedge bracket may contact the fuel tank, potentially damaging the tank and leading to a fuel leak.

Hazard A fuel leak increases the risk of fire, which could result in severe injury or death as well as damage to property.

What to do Consumers should immediately stop using their boat and contact their authorised Malibu Boats dealer to arrange an appointment for repair, free of charge. Malibu Boats will contact affected consumers to advise them of the recall.

Contact details Consumers can contact Malibu Boats on 02 6040 1174 or email via recalls@malibuboats.com.au

See productsafety.gov.au for Australian product recall information