

Product Safety Recall



**Avanti Corsa SL
Bicycles and
Framesets
MY2014-2018**



**Avanti Corsa ER
Bicycles and
Framesets
MY2016-2018**



**Avanti Giro C
Bicycles
MY2017-2018**

**Sold by Authorised Avanti Dealers
between 21 January 2013 and 7 May 2020**

Defect In Avanti Corsa SL Bicycles and Framesets, the seat clamp bolts may break or the bicycle frame may develop cracks at the intersection with the seat clamp bolts.

In Avanti Corsa ER Bicycles and Framesets and Avanti Giro C Bicycles, the seat clamp bolts may break.

Hazard The seat post may slide downwards inside the frame. If this occurs while the user is riding the bicycle, there is an increased risk of an accident or injury to the rider or bystanders.

What to do Consumers should stop riding the bicycle immediately and contact the place of purchase to arrange for a replacement seat post kit to be fitted, free of charge.

Contact details Consumers should contact their nearest Authorised Avanti Dealer, or Sheppard Cycles Australia on 1300 883 305, csaustralia@sheppardcycles.com or www.avantibikes.com/au

**See productsafety.gov.au for
Australian product recall information**