


Product Safety Recall



Metforce Pty Ltd

Metforce Pty Ltd wishes to advise of a recall of all frameless pool fence glass door LOCKABLE latches.

Product Codes:

LATCH 316 G2G / LATCH 316 G2W / LATCH 316 G2G INSWING
LATCH 316 G2G OUTSWING / LATCH 316 G2P RND

**ONLY THE LATCHES THAT ARE LOCKABLE AND SUPPLIED WITH
KEYS ARE AFFECTED**

Defect The products do not comply with Australian Standard AS1926.1 2012 Safety Barriers for Swimming Pools section 2.4.2.1 (b). If the gate is open, turning the key in the striker component of the gate latch may cause the gate to remain locked in the open position.

Hazard If the glass gate remains unlocked, the pool or spa area will be unsafe to access, posing a potential drowning risk.

What to do Consumers are to secure the pool gate until the replacement has been installed.

Contact details If your latch is lockable and you are concerned that it may be faulty, please contact Metforce on 08 9302 3686 immediately.

You can also email sales@metforce.com.au or visit us on www.metforce.com.au
A replacement latch will be sent to you immediately with simple instructions on how to replace the faulty part.

**See productsafety.gov.au for
Australian product recall information**