

# Product Safety Recall

## Mercury Mariner 30-225hp Inline Fuel Filter (OSFF879)



**Sold by Outboard Spares  
between 1 October 2020 and 23 February 2021**

**Defect** The fuel filter may not be adequately sealed and may leak fuel.

**Hazard** A fuel leak increases the risk of fire, which could result in severe injury or death as well as damage to property.

**What to do** Consumers should stop using the product and contact Outboard Spares for a full refund or credit.

**Contact details** Consumers can contact Outboard Spares on 1300 696 882 or at [info@outboardspares.com.au](mailto:info@outboardspares.com.au)

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**