

Product Safety Recall



Kubota Z400 Series Mower

Z411KW-48-AU (serial nos. 10113 - 10302)

Z421KW-54-AU (serial nos. 10079 - 10258)

- Defect:** The roll over protection system (ROPS) retention bolts may not have been tightened during the final assembly process.
- Hazard:** Under some operating conditions, the ROPS retention bolts can become loose, putting the operator at risk of injury.
- What to do:** To avoid personal injury customers should stop using the affected mowers until the mower has been inspected and ROPS retention bolts torqued by your Kubota dealer at no charge.
- Contact details:** Contact your local Kubota dealer Kubota.com.au/authorised-dealerships
Or Kubota Australia on 03 9394 4400 or kubota.com.au

**See productsafety.gov.au for
Australian product recall information**