

# Product Safety Recall

## Packster 70 Electric Cargo Bicycle



Sold by Dolmiti, Dutch Cargo Bike, E-stralian, Omafiet's Dutch Bicycles and Pemby t/as Electric Bikes Brisbane between 1 February 2021 and 6 October 2021

### Defect

The front pulley's clamping bolts may not be tightened properly and may allow the steering wire to slip.

### Hazard

If the steering wire slips, the rider will lose steering control. This may lead to an accident causing injury or death.

### What to do

Consumers should stop using the bicycle and return it to the place of purchase for a full refund.

### Contact details

For more information, consumers can contact Riese & Müller on [recall@r-m.de](mailto:recall@r-m.de)

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information