

Product Safety Recall

Specialized Australia Pty Ltd

Roubaix, Ruby, Diverge and Sirrus bicycles

Sold by authorised Specialized retailers between 01/09/2016 to 31/12/2018



Identification Below is a list of affected bicycles by model year:

2017	ROUBAIX	RUBY	2018	ROUBAIX	RUBY	DIVERGE	SIRRUS	2019	ROUBAIX	RUBY	DIVERGE	SIRRUS
S-WORKS	X	X	S-WORKS	X	X	X		S-WORKS	X	X	X	
PRO	X	X	PRO	X			X	PRO			X	X
EXPERT	X	X	EXPERT	X	X	X	X	EXPERT	X	X	X	X
COMP	X	X	COMP	X	X	X		COMP	X	X	X	X
ELITE	X	X	E5 COMP			X		E5 COMP			X	
			SPORT	X	X	X		SPORT	X	X	X	
			ELITE	X	X			BASE	X	X	X	
			BASE	X	X							

Defect The steerer tube collar may be susceptible to stress corrosion cracking which may result in sudden loss of steering control.

Hazard Sudden loss of steering control increases the risk of accident, causing serious injury to the rider and potentially other road users.

What to do Consumers should cease using the affected bicycles immediately and return them to their nearest authorised Specialized retailer for a replacement steerer tube collar, free of charge.

For further information, consumers can phone Specialized Rider Care on 1300 499 330 or visit <https://www.specialized.com/au/en>

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**