

Product Safety Recall

KIPRUN GPS 500 and KIPRUN GPS 550 Watches



Sold online at www.decathlon.com.au/ and in Decathlon (Australia) stores from 1 March 2021 to 18 December 2021

Identification: KIPRUN GPS 500 - 8527648 and 8527647
KIPRUN GPS 550 - 8527651 and 8527652

Defect: The battery in KIPRUN GPS 500 and 550 watches can overheat during charging and/or in use.

Hazard: If the battery overheats, there is a risk of burns to the user who is wearing the watch or a fire resulting in serious injuries or death.

What to do: Consumers should immediately stop using the products and return them to Decathlon for a full refund.

Contact Details: For further information, contact Decathlon Customer Relations Centre by chat on www.decathlon.com.au or via email at contact.australia@decathlon.com (Monday to Sunday, 9am - 8pm AEST).

**See productsafety.gov.au for
Australian product recall information**