

Product Safety Recall

Sea-Doo Spark Audio Portable System

Part Number
295100797
295100867



How to identify a defective audio-portable system:

Numbering under bar code is structured as follows:
DAY 001 - 365 YEAR 19 - 21
NNNNN DAYYR XXXX

For production year 19 or 20: Audio Portable System is included in campaign.
For production year 21: Audio Portable System might be included in campaign,
according to table below.

| Production Year 21 | Included in Campaign? |
|--------------------|-----------------------|
| 00021 to 11321 | Yes |
| 11421 to 36521 | No |

Sold by authorised Sea-Doo dealerships as an accessory or mounted on certain Sea-Doo Spark personal watercraft (Model Years 2019-2021 and certain 2022) from 14 December 2018 to 18 March 2022

Defect: The tabs of the Audio Portable System may break and cause the Audio Portable System to dislodge from its mount.

Hazard: If the Audio Portable System dislodges from its mount, there is a risk of serious injury or death to the user or passenger.

What to do: Consumers should remove the portable audio system from their personal watercraft before using it.

BRP will repair all affected portable audio systems free of charge. Repairs are expected to commence from the end of June 2022.

To find a local Sea-Doo dealer, visit <https://au.sea-doo.com/dealer-locator.html>

Contact Details: For further information, please contact BRP by phone on 1800 531 996.

See productsafety.gov.au for
Australian product recall information