

Product Safety Recall

Spalding Momentous Ez Assembly Acrylic Portable Basketball Hoop System



Defect: Due to a manufacturing defect, the backboard may not have been welded to the supporting pole properly and may fail.

Hazard: If the welding fails the backboard may separate from the supporting pole, increasing the risk of serious injury.

What to do: Consumers should stop using the product immediately and contact Russell Australia. Russell Australia will offer consumers collection of the product and either a full refund or an alternative product of equivalent or better value, at Russell Australia's expense.

Contact details: For more information, consumers can contact the Spalding Customer Service Team by phone on 1300 654 766 (Monday to Friday, 9am to 5pm AEST) or via email info@spalding.com.au

**See productsafety.gov.au for
Australian product recall information**