

Product Safety Recall

UBCO 2x2 Work Bike Electric Motorcycle MY2021



The product is available from authorised UBCO dealers
between 1 January 2021 to 16 March 2022

Description: 2 wheel drive electric off-road motorcycle

Available in black or white

Model Year 2021

Defect: A part of the wheel hub may loosen during operation causing the gear and hub motor to touch.

Hazard: If the gear and hub motor touch during use, this may cause the wheels motor to stop suddenly.

This can increase the risk of an accident or injury to the driver or bystanders. In the event of a serious accident, this may result in death.

What to do:

Consumers should stop riding the motorcycle immediately and contact their local authorised UBCO service dealer to arrange for an inspection and if necessary repair of the vehicle, free of charge.

Consumers can visit <https://ubco.com/pages/dealer-locator> for a full list of authorised UBCO dealers.

For further information, consumers can contact UBCO via phone call at 0407 849 281 or via email at supportAU@ubcobikes.com

See productsafety.gov.au for
Australian product recall information