

Product Safety Recall



TrackMaster Tyre

Available for sale by Goannatracks Overland Expeditions between 18 August 2017 and 1 May 2018

DEFECT The tyres side wall may fail and lose air if used under inflated or overloaded.

HAZARD If the side wall loses air whilst the vehicle is being driven, this may increase the risk of an accident or injury to vehicle occupants, and other road users.

WHAT TO DO Consumers should immediately cease using product and contact Goannatracks Overland Expeditions to arrange a replacement.

Contact details For more information, contact Goannatracks Overland Expeditions via email on goannatracks@gmail.com

**See productsafety.gov.au for
Australian product recall information**