

Product Safety Recall



Spiky Bounce Ball

Defect The ball does not comply with the mandatory safety standards for toys for children up to and including 36 months of age (Consumer Protection Notice No. 14 of 2003, as amended by Consumer Protection No. 1 of 2005). The squeaker may be removed from the ball.

Hazard If the squeaker is removed from the ball it may pose a potential choking hazard to young children.

What to do Consumers should stop using the ball and return it to the place of purchase for a full refund.

Contact details Consumers can go to <http://newdimensionoz.com.au> for further information.

**See productsafety.gov.au for
Australian product recall information**