

# Product Safety Recall

## iCandy Peach 2018 Pram



**CORRECT**  
CAP IN PLACE

**INCORRECT**  
CAP MISSING

Comes in Beluga, Indigo, Dove Grey, Twilight and Cerium  
Sold between 2 August 2018 and 31 December 2019

**Defect:**

The pram bumper bar may be missing a plastic cap in the hinge, exposing a small hole when the bumper is hinged back.

**Hazard:** If the cap is missing and the bumper bar is hinged back, a child may put their fingers in the exposed hole, posing an entrapment hazard and injury risk to the child.

**What to Do:**

Consumers should check each hinge on the bumper bar for a missing cap. Tobil & Co Pty Ltd will post a replacement bumper to consumers with an affected product.

**Contact Details:**

For more information, contact Tobil & Co Pty Ltd on 03 8555 2431 or via email [info@tobil.com.au](mailto:info@tobil.com.au)

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**