

Product Safety Recall



**Polaris Spare Parts and Youth All-Terrain Vehicle (ATV):
MY2009–2017: RZR 170 and spare part numbers 0454640
(breather gasket) and 0454808 (engine).**

Sold at authorised Polaris Dealers since 2009.

Defect: Parts may contain asbestos.

Hazard: Currently available information indicates that the product poses no measurable asbestos-related health risk during use of the vehicle. Caution must be taken if carrying out repairs/maintenance.

What to do: Any work involving these vehicles should be carried out by an authorised Polaris dealer. Procedures will be implemented to ensure that the vehicles are handled correctly by Polaris dealers. Affected consumers will have the part replaced at no charge when normal in-service replacement is required.

Contact details: For further information consumers can call the Customer Service Department on 1800 982 593 or go to www.polarisindustries.com.au.

**See productsafety.gov.au for
Australian product recall information**