

Product Safety Recall



OX FIBREGLASS PLATFORM LADDER

Model Numbers: OX-T332103, OX-T332104, OX-T332105, OX-T332106, OX-T332107, OX-T332108 & OX-T332109.

Sold from July 2012 to April 2013

Defect: The ladders do not comply to with the mandatory safety standard because of an issue with the platform hinge.

Hazard: The defect may result in or contribute to falls from the ladder.

What to do: Do not use the ladder. Return your ladder to the supplier you purchased it from and arrangements will be made for the ladder platform to be replaced or repaired free of charge. You will be notified when your ladder is ready to be collected – this should take between 7 & 10 days.

Ladders purchased after April 2013 have the new platform hinges and are suitable for use.

Supplier Contact Details for more information:

OX Group International Pty Ltd

Ph: 02 8845 6600.

Email: sales@oxgroup.com.au

www.oxtools.com.au



See www.recalls.gov.au for
Australian Product Recall Information