

**Specialized Bicycle Components, Inc.**  
251 Salmon Street Port Melbourne VIC 3207

**IMPORTANT RECALL NOTICE!**

**TO:**

**PLEASE READ THIS NOTICE CAREFULLY**

**IMPORTANT RECALL NOTICE!**

In cooperation with the Australian Competition and Consumer Commission, Specialized Bicycle Components, Inc. (“Specialized”) is voluntarily recalling the front forks on all models of the 2012 Tarmac SL4, 2013 Tarmac SL4, 2013 Crux, and 2013 Secteur Disc bicycles and framesets.

The front fork steerer tube can break, posing a fall hazard. Please stop riding immediately and return your bicycle to an Authorized Specialized Retailer for a free inspection and, if appropriate, repair. Your fork will need to be shipped to our Salt Lake City facility for this work.

Specialized apologizes for any inconvenience to you as a valued customer and is taking this step to ensure quality and safety. When you return your bicycle, please bring this postcard with you to receive a complimentary \$100 store credit toward the purchase of Specialized branded merchandise. The complimentary credit is not refundable for cash and must be used in a single purchase transaction.

Please direct any questions you may have to your local Authorized Specialized Dealer



Specialized Bicycle Components, Inc.  
251 Salmon Street Port Melbourne VIC 3207