

Product Safety Recall

215/60R16 95V SUPERCAT TYRE MADE IN THAILAND

The tyres affected are 215/60R16 95V Supercat, **made in Thailand**.

These tyres were imported by Bridgestone Australia Ltd and sold in Australia between 1st May 2010 to 8th Feb 2016 through Bridgestone Select, Bridgestone Service Centres and Bridgestone Tyre Centres.



Defect

Bridgestone has detected that some of these tyres may exhibit an issue with the tread / belt leading to possible rapid loss of air pressure.

Hazard

If the defect occurs, there may be loss of vehicle control which may pose a hazard to the driver and/or other road users.

What to do

If you believe you have an affected tyre, please either call toll free number **1800 354 864** or email customerservice@bridgestone.com.au to arrange a replacement of the affected tyres. The affected tyres will be replaced free of charge.

Further information can be obtained on the internet site www.bridgestonetyres.com.au.

See www.recalls.gov.au for
Australian Product Recall Information