

## Product Safety Recall



**Polaris Spare Parts and Polaris Youth All-Terrain Vehicles (ATVs): MY 2001 – 2018: Outlaw 50, Outlaw 90, Outlaw 110, Sportsman 90, Sportsman 110, Predator 50, Predator 90, Scrambler 90. Part numbers: 0453578, 0453538 and 0453580 (gaskets), 0450204 (clutch carrier).**

Sold at authorised Polaris Dealers since 2000.

**Defect:** Parts may contain asbestos (gaskets, clutch carrier).

**Hazard:** Currently available information indicates that the products pose no measurable asbestos-related health risk during use of the vehicles. Caution must be taken if carrying out repairs/maintenance.

**What to do:** Any work involving these parts and vehicles should be carried out by an authorised Polaris dealer. Procedures will be implemented to ensure the vehicles and parts are handled correctly by Polaris dealers. Affected consumers will have the parts replaced at no charge when normal in-service replacement is required.

**Contact details:** For further information consumers can call the Customer Service Department on 1800 982 593 or go to [www.polarisindustries.com.au](http://www.polarisindustries.com.au).

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**