

# Product Safety Recall

**Trek Bicycle Corporation (Australia) Pty Ltd - Trek 720 Disc bicycles and certain Bontrager aftermarket wheels**



## **Defect**

The front brake caliper could engage with a broken spoke, causing the rider to lose control of the bicycle.

## **Hazard**

If the rider loses control of the bicycle, the rider may fall and be injured.

## **What to do**

Consumers with the affected Trek model bicycles or bicycle wheels should stop using their bicycle and take it to a Trek retailer for inspection and repair immediately. Affected bicycles will be fitted with replacement wheels and owners of aftermarket wheels will receive a replacement wheel.

Consumers will also receive a coupon worth AUD \$120 to spend at Trek retailers on Trek or Bontrager products.

## **For more information**

Phone 02 6173 2400 [Monday - Friday from 08:30-17:30, AEST] or visit  
[www.trekhikes.com](http://www.trekhikes.com)

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**