

Product Safety Recall



Tridon Australia — MA8000 battery charger

Defect: The affected products were received fitted with a 240V C13/C14 monitor style plug and socket for charging the 12v internal batteries.

Hazard: A consumer may connect a 240v monitor style lead from mains power into the 12v charging port on the jump starter which may pose a fire or electric shock hazard.

What to do: If you are in possession of a MA8000 jump starter that is fitted with the C13 socket indicated above, please return the jump starter, and charger it was supplied with, to the nearest store for collection and repair or contact Tridon at sales@tridon.com.au.

See productsafety.gov.au for
Australian product recall information