

## **Product Safety Recall**



## Do you own this product?

## **Tacx NEO Bike Plus Trainer**

Dates sold: 1 January 2023 - 24 June 2024



Why the product is recalled: A power supply board inside the bike can overheat and catch fire.

**Hazard:** There is a risk of serious injury from burns and/or property damage if the power supply board overheats and catches fire.

## What consumers should do

- 1. Disconnect the Trainer from the power source.
- 2. Only use your Trainer in standalone mode, disconnected from the power source, until you have completed the steps below.
- 3. Dispose of the original power cord in accordance with local requirements.



- 4. Visit <a href="http://www.garmin.com/NBP">http://www.garmin.com/NBP</a> PowerSupply to order a replacement power cord free of charge.
- 5. After you receive the new replacement power cord, update your Trainer software to version 5.2.0 or newer.

**Do not use** a third-party power cord with your trainer. Only use the power cord and adapter provided by Garmin/Tacx.

For more information consumers can visit www.garmin.com/fitness/servicealerts



Contact Tacx B.V. 1800 244 143 au.consumer.sse@garmin.com



Purchased from: Garmin website (garmin.com/en-AU), Achieva Agents, 99 Bikes, The Odd Spoke, Urban Pedaler, Fast Lane Bike Shop, ABC Bikes, City Bicycle Express, Health Management Group Pty Ltd, Adventure Online t/a Pushys Online

PRA 2024/20254

See **productsafety.gov.au** for Australian product recall information