

Product Safety Recall

FUJI BICYCLES and KESTREL BICYCLES

MODELS: 2009 Fuji D6 Pro Bicycles
2010 Fuji D6 Pro Bicycles
2009 Kestrel Evoke SL Bicycles
2009 Kestrel Talon SL Tri Bicycles



2009 & 2010 Fuji D6 Pro Bicycle

2009 Kestrel Evoke SL Bicycle

2009 Kestrel Talon SL Tri Bicycle

Hazard:

The bicycle handlebar stems can corrode and break, causing the rider to lose control and crash.

Remedy: Replacement of handlebar stems

What to do: Consumers should immediately stop using the bicycles and return them to the nearest Fuji or Kestrel bicycles dealers for a free handlebar stem replacement.

Contact: Rebel Sports at 1300 654 502
www.rebelsport.com.au

See www.recalls.gov.au for
Australian Product Recall Information