

Product Safety Recall



**TJM Recovery Gear Snatch Strap 8,000KG 9M
(867TJMS8000)**

Also found in the following products:

**867TJMREKIT1 – TJM Recovery Gear Snatch Strap Kit
867TJMREKIT2 – TJM Recovery Gear Large Recovery Kit
Sold at TJM Stores 26th June 2017 – 25th May 2018**

Defect: Product Serial number is missing or illegible on the product label and is not compliant with the relevant mandatory safety standard.

Hazard: Product is not traceable to a manufacturing date if there is a safety issue with the product.

What to do: Consumers who have purchased an 8,000KG Snatch Strap (867TJMS8000) or TJM Recovery Kits (867TJMREKIT1 & 867TJMREKIT2) and after inspection believe that the serial number is missing or illegible, must return the Snatch strap to any TJM store for a replacement or refund.

Contact Details: You can contact your nearest TJM Store for further information. To find your nearest TJM Store, visit www.tjm.com.au

**See productsafety.gov.au for
Australian product recall information**