

RECALL TO REPAIR

dash[™]



phil&teds[®] dash[™] buggy

Sold in Australia from
March 2008 to August 2011

Identification: *dash*[™] logo is on main seat and cushion liner.

Hazard: Main hinge may pose a finger tip injury risk while folding or unfolding the buggy.

Remedy: Install cover kit, available free. It does not require the return of your stroller. Install easily, in-home, tool free.

Action: **PLEASE REGISTER ONLINE** or call to receive your FREE in-home repair kit with simple step by step instructions

web: www.philandteds.com/support
phone: 1800-888-586