

## Product Safety Recall



### Products Information

#### Products Part Number and Descriptions:

JT412      **Orcon 1200kg Trolley Jack** *Batch #:* 14019/0709  
JT414      **Orcon 1400kg Trolley Jack** *Batch #:* 4522/0308

#### Defect:

The jacks failed to meet the serviceability requirements of section 6.2 of AS/NZS 2615-2004.

#### Hazard:

The maximum rated load capacity maybe subject to deterioration over the lifespan of the Jacks.

#### Effected Products:

JT412 batch #: 14019/0709 supplied from October 2009.  
JT414 batch #: 4522/0308 supplied from April 2008 .

### What Should Consumers do:

#### Consumer Actions:

Stop using your jack immediately and return to the place of purchase, for an exchange or refund.

### Further Information:

#### Supplier Information:

Haigh Australia Pty Ltd  
64 Argyle Parade  
Darra, Queensland, 4076  
Ph: (07) 3713 9345

#### Supplier Web site:

[www.haigh.com.au](http://www.haigh.com.au)

#### Supplier Contact:

Chris Roberts

**See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information**