


Product Safety Recall

Thule Rapid Fixpoint XT Kits installed on certain vehicles



**Sold by Thule Australia and Go Active Outdoors
between 17 December 2019 and 1 June 2020**

Defect The kit's bolts are too small and may result in the kit not being properly secured to the roof of the vehicle. This may cause the kit and any items attached to it to become detached from the roof.

Hazard If the roof rack or any items attached to it detaches from the vehicle, there is an increased risk of an accident and injury to the vehicle occupants and other road users.

What to do Consumers should stop using their Fixpoint XT Kit and remove it from their vehicle.

To identify whether their kit is affected by the recall, consumers should visit <https://www.thule.com/en-gb/product-recall/thule-fixpointxt-kit-recall> If affected, consumers should contact the place of purchase for a full refund or a replacement Fixpoint XT Kit, installed free of charge.

Contact details Consumers can contact Thule AB at fixpointkits@thule.com

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**