

# Product Safety Recall

## Front Rack Kit for Cannondale Treadwell Bicycles



Sold by authorised Cannondale dealers  
between 1 April 2019 and 13 July 2020

**Defect** The front rack may detach from the bicycle.

**Hazard** If the front rack detaches from the bicycle there is an increased risk of an accident or injury to the rider or bystanders.

**What to do** Consumers should stop using the rack and remove it from their bicycle. For instructions on how to remove the rack, visit <https://www.cannondale.com/en-au/safety-and-recalls>

Parts are expected to become available in September 2020. Consumers will be asked to contact the place of purchase to organise for the front rack attachment system to be replaced, free of charge.

**Contact details** Consumers can contact PSI Cycling by email at [service@psicycling.com.au](mailto:service@psicycling.com.au) or by phone on 03 8327 8080.

See [productsafety.gov.au](https://www.productsafety.gov.au) for  
Australian product recall information