

# Product Safety Recall

## CamelBak Podium and Peak Fitness Water Bottle Caps

Only water bottle caps with the following date codes are affected:  
H19039, H19175 and H19063 (located on the underside of the cap)



Sold nationally and online through bicycle stores,  
outdoor and adventure stores, and sports stores  
between 6 April 2019 and 6 April 2021

**Defect** The small silicone valve in the cap of affected water bottles may separate from the cap.

**Hazard** If the small silicone valve separates from the cap, it may pose a choking hazard.

**What to do** Consumers should stop using the affected caps and visit <https://www.camelbak.com.au/recall> to obtain a replacement cap or a full refund. To obtain a refund or replacement, consumers will be requested to provide a photograph of the date code on the affected cap.

**Contact details** For more information, consumers can visit <https://www.camelbak.com.au/recall>

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information