

# Product Safety Recall

## 99 BIKES Pty Ltd – Pedal Clipper 54cm Electric Bike



Pedal Clipper 54cm electric flat-bar road bike  
Affected products have a serial number on the bottom bracket within the range  
KL2100501 - KL2100900  
Supplied between 1 March 2022 and 23 December 2022.

**Defect:** The seat post clamp may fail causing the bicycle saddle (seat) to dislodge.

**Hazard:** If the bicycle saddle dislodges during use, it increases the risk of accident and serious injury to the rider.

**What to do:** If consumers have previously upgraded or replaced their seat post they do not need to replace it again. Consumers should contact 99 Bikes with their serial number to notify them if they have previously replaced the seat post.

Consumers that are using the original seat post should stop using the bicycle immediately and return it to their nearest 99 Bikes store for a replacement seat post. Visit <https://www.99bikes.com.au/stores> to find the nearest store.

Consumers that are in remote areas and unable to go to their nearest store should contact 99 Bikes on 1800 990 523 to arrange a replacement part to be sent to them.

**See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information**