

Product Safety Recall

Daiso Industries (Australia) Pty Ltd
Various button battery products

JAN 454989237697



JAN 4549892380105



JAN 4549131445329



JAN 4549131445312



JAN 4549131472110



JAN 4549131256628



Products affected

LED Candle Lamp, LED Candle Lantern, LED Arm Band, LED Wrist Light, Calculator with Ruler and Mini Stopwatch. JAN number can be located on the product packaging.

Defect The battery compartment may not be adequately secured allowing possible access to the button battery if the product is dropped on a hard surface.

Hazard If young children gain access to the button batteries and ingest them, they may suffer internal burn injuries, which can result in serious illness and even death. In addition, the batteries may pose a choking hazard to young children

What to do Consumers should immediately cease using the affected products and return the products to any Daiso store (refer to <https://www.mydaiso.com.au/stores>) for a full refund or exchange.

Contact Details: You can contact Daiso by phoning (03) 9516 4400, via email at info@daisojapan.net.au

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**