Product Safety Recall





BMC Teammachine SLR 01 DISC Bicycles and Frame Sets

Sold nation-wide between June 2017 and November 2019

Defect The bicycle fork steerer tube may crack and potentially snap during regular use.

Hazard If the bicycle fork breaks, the rider may lose control of the bicycle, which may increase the risk of an accident or injury to the rider.

What to do Consumers should stop riding the bicycles immediately and contact their BMC retailer to arrange an inspection of the fork to identify if it is safe to continue riding or if a replacement fork needs to be fitted.

Contact details For further information, consumers can contact Advanced Traders on 1300 361 686 or by visiting http://www.advancetraders.com.au/

See www.recalls.gov.au for Australian Product Recall Information