

PRODUCT SAFETY RECALL

Toro Z Master Ride-on Mowers and TX 427 Compact Utility Loaders with Kohler Engines



Toro Australia Pty Ltd is conducting a product recall of Kohler Engines in the Toro Z Master Ride-on Lawnmowers and TX 427 Toro Compact Utility Loaders listed below.

Model	Name	Year	Serial Number
74915	Toro 5000 Series Z Master	2009 - 2013	290000101-313000776
74915CP	Toro Z Master G3	2011	311000101-311000200
22321	Toro TX 427 Narrow Track	2009 - 2013	290000101-313000200
22322	Toro TX 427 Wide Track	2009 - 2013	290000101-313000200

The products were sold nationally in Authorised Toro dealers during 2009-2014. The model and serial numbers are located on a metal plate on the front of the mower and below the seat on the Toro Z master ride on mowers. The model and serial numbers are located on a metal plate on the front right side of the Toro compact utility loaders. Contact Toro using the contact details below if you have any questions regarding whether your product is included in the recall.

DEFECT: The Kohler engine electrical system can fail.

HAZARD: If the Kohler engine electrical system fails it may cause a fire hazard.

WHAT TO DO: Users should stop using the machine immediately and contact a Toro dealer to schedule a free repair.

CONTACT DETAILS: If you have any questions regarding this issue, including whether your product is included in this recall or for the details of your local Toro dealer please contact Toro on 1800 356 372 or email ProductRecall.AU@toro.com

See www.recalls.gov.au for Australian product recall information